



SW ON	FUNCTION	
	IN	OUT
#1	A	DATA
#2	B	DATA
#3	B	A
#4	DATA	A
#5	A	B
#6	DATA	B

# FDX55

## RS232/422 DROP AND REPEAT 1 FIBER

### D-1026 + D-1029